

MR3287-12

Serial No. 10/773,399

Response to Office Action dated 4 August 2004

Please replace the ABSTRACT, page 8, with the following amended

ABSTRACT:**ABSTRACT OF THE DISCLOSURE**

A screw including a head, a shank under the head in a whole body, and a thread helically built upon the outside trunk of the shank; wherein, said The thread ~~projected projects~~ from the circular trunk of the shank ~~and is consisted~~ consists of an upper flight flank, a low flight flank, and an peak edge on the joint line of the upper and low flights flanks, and an even number of axial slots formed on the thread. ~~The feature is that every~~ Every axial slot is beveled with a back angle to form a ~~sheared section~~ tilt surface from the upper flight flank to the low flight flank to form a cutting edge for facilitating to rapid fastening with a smaller tapping torque as tapping in.

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.